

Perkins Aircraft Services PMA Product & Repair Services Bulletin



IAI Westwind
1121/1123/1124
 Outer Windshields, Inner Windshields,
 Side Cockpit Windows, Direct Vision
 Windows, Passenger Windows

Perkins Aircraft Capabilities

| | |
|--|---|
| Outer Windshields P/N 5343030-ALL#s | Delamination Repair Remove Internal Bubbles Due to Overheat Replace Seals Polishing & Scratch Removal Testing For Serviceability |
| Inner Windshields P/N 5343025-ALL#s | On Aircraft Polishing & Scratch Removal Repair Burnt Electric Probe Holes Testing For Serviceability On-Site Installation Available FAA/PMA REPLACEMENT PART P/N PAS5343025- ALL#s |

| | |
|---|--|
| <p>Side Cockpit Windows L/H Outer P/N 343017-3 L/H Inner P/N 343017-5 R/H Outer P/N 343003-4 R/H Inner P/N 343003-8</p> | <p>On Aircraft Refinishing Overhaul Complete Assembly Testing For Serviceability On-Site Installation Available FAA/PMA REPLACEMENT PART L/H Outer P/N PAS343017-3 FAA/PMA REPLACEMENT PART L/H Inner P/N PAS343017-5 FAA/PMA REPLACEMENT PART R/H Outer P/N PAS343003-4 FAA/PMA REPLACEMENT PART R/H Inner P/N PAS343003-8</p> |
| <p>Direct Vision Windows P/N 343017-15/-17</p> | <p>On Aircraft Refinishing Testing For Serviceability FAA/PMA REPLACEMENT PART P/N PAS343017-15/-17</p> |
| <p>Passenger Windows P/N 343016-501</p> | <p>On Aircraft Refinishing Testing For Serviceability FAA/PMA REPLACEMENT PART P/N PAS343016-501</p> |

