

Perkins Aircraft Services PMA Product & Repair Services Bulletin



Ratheon King Air F90 / 350
 Main Windshields, Side Crew
 Compartment (D-Panel), Storm
 Windows, Passenger Windows

Perkins Aircraft Capabilities

Main Windshields P/N 101-384025-ALL#s	Delamination Repair Remove Internal Bubbles Due to Overheat Polishing & Scratch Removal Testing For Serviceability
Side Crew Compartment (D-Panel) P/N 50-420066-ALL#s P/N 101-420081-ALL#s	On Aircraft Refinishing Testing For Serviceability On-Site Installation Available FAA/PMA REPLACEMENT PART P/N PAS50-420066-ALL#s FAA/PMA REPLACEMENT PART P/N PAS101-420081-ALL#s
Storm Windows P/N 101-420122-ALL#s	On Aircraft Refinishing Testing For Serviceability FAA/PMA REPLACEMENT PART P/N PAS101-420122-ALL#s

Passenger Windows
P/N 101-430183-5

On Aircraft Refinishing
Delamination Repair
Testing For Serviceability
On-Site Installation Available
FAA/PMA REPLACEMENT PART P/N PAS101-430183-5

