



## **Perkins Aircraft Services Inc.**

2600 South Cherry Lane, Suite 162

Fort Worth, TX 76116

**REPAIR STATION NUMBER: JKQR257L**

**PMA FACILITY NUMBER: PQ0682SW**

### **WARRANTY AGREEMENT**

The enclosed warranty for our product is as strong and effective as we can make it. Our windshields and windows are warranted against defective materials and workmanship. The warranty is limited to the replacement of the defective parts. Prior to installation the protective coating should be peeled, and the part inspected. After inspection, the window may be recovered with the protective coating which was removed. There is no allowance for labor costs incurred during installation and removal of a defective part. Return freight is not covered.

***Perkins Aircraft Services will not assume any liability for damages due to improper installation, modification, unauthorized repair, or any damage incurred during shipping.***

***Our warranty does not cover cracking, crazing, scratches, or breakage.***

#### **NEW PMA PARTS ONLY**

Perkins Aircraft Services has a one-year guarantee on **NEW PMA PARTS**.

#### **REPAIR PARTS ONLY**

Perkins Aircraft Services has a ninety (90) day warranty on **REPAIRED PARTS** on work performed by Perkins Aircraft Services. Does not include any electrical or heating components, or glass breakage.

We wish to thank you for purchasing our product and hope that we may continue to be of service to you. Please call if you have any questions.

**sales@perkinsaircraft.com**  
**(817) 877-1966 • (800) 880-1966 • FAX (817)-877-4339**